

Events by distance



SDD

VIN: SALLAAA64AA550056
 Model: Land Rover L319 Discovery 3i4
 Session creation: Mon 10-Feb-2020 15:34
 Session printed: Mon 10-Feb-2020 15:36
 Current odometer: 169,559km

DTC	ECU	Distance ▼	Time	Description	Status	Options	Relevance
169,543km - Event 3							
P042C-00	PCM	169,543km	10.2.20 14:49	Catalyst Temperature Sensor Circuit Low (Bank 1, Sensor Circuit 2) - No sub type information			16%
168,373km - Event 2							
P244B-00	PCM	168,373km	9.2.20 3:05	Diesel Particulate Filter Differential Pressure Too High - No sub type information			33%
U0401-68	ABS	168,373km	9.2.20 3:05	Invalid data received from ECM/PCM A - Event information			
U0416-68	RLM	168,373km	9.2.20 3:05	Invalid Data Received From Vehicle Dynamics Control Module - Event information			100%
168,080km - Event 1							
U0128-00	IPC	168,080km	8.2.20 18:01	Lost communication with park brake control module - No sub type information			
ECUs Not Responding							
TCM							

Events by distance



SDD

VIN: SALLAAA64AA550056
 Model: Land Rover L319 Discovery 3i4
 Session creation: Wed 11-Mar-2020 10:51
 Session printed: Wed 11-Mar-2020 10:52
 Current odometer: 170,876km

DTC	ECU	Distance ▼	Time	Description	Status	Options	Relevance
170,768 to 170,769km - Event 3							
P244B-00	PCM	170,768km	11.3.20 1:50	Diesel Particulate Filter Differential Pressure Too High - No sub type information			66%
U0401-68	ABS	170,768km	11.3.20 1:50	Invalid data received from ECM/PCM A - Event information			16%
U0416-68	RLM	170,769km	11.3.20 1:50	Invalid Data Received From Vehicle Dynamics Control Module - Event information			100%
169,684km - Event 2							
B123B-15	BCM	169,684km	9.3.20 2:06	Front right Turn Indicator - Circuit short to battery or open			
B123A-15	BCM	169,684km	9.3.20 2:07	Front left Turn Indicator - Circuit short to battery or open			
169,565km - Event 1							
U0128-00	IPC	169,565km	8.3.20 18:18	Lost communication with park brake control module - No sub type information			
Unknown Events							
U0159-00	IPC	-----km	--/-- --:--	Lost Communication With Parking Assist Control Module A - No sub type information			



Events by distance

VIN: SALLAA64AA550056
 Model: Land Rover L319 Discovery 3/4
 Session creation: Mon 04-May-2020 08:50
 Session printed: Mon 04-May-2020 08:51
 Current odometer: 172,260km

DTC	ECU	Distance ▼	Time	Description	Status	Options	Relevance
172,120km - Event 3							
P042A-62	PCM	172,120km	4.5.20 4:32	Catalyst Temperature Sensor Circuit (Bank 1, Sensor Circuit 2) - Signal compare failure			
170,929 to 170,930km - Event 2							
P244B-00	PCM	170,929km	29.4.20 13:39	Diesel Particulate Filter Differential Pressure Too High - No sub type information			100%
U0401-68	ABS	170,929km	29.4.20 13:39	Invalid data received from ECM/PCM A - Event information			25%
U0416-68	RLM	170,930km	29.4.20 13:39	Invalid Data Received From Vehicle Dynamics Control Module - Event information			
170,885km - Event 1							
U0128-00	IPC	170,885km	29.4.20 2:15	Lost communication with park brake control module - No sub type information			